




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K



0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K



0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K



0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K

