




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, T = 1092 K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, T = 1092 K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, T = 1092 K




0.565% C₂H₅OH in N₂, $\Phi = 0.61$, $p = 1.0$ atm, T = 1092 K




$0.565\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0 \text{ atm}$, $T = 1092 \text{ K}$




$0.565\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0 \text{ atm}$, $T = 1092 \text{ K}$




$0.565\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0 \text{ atm}$, $T = 1092 \text{ K}$




$0.565\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0 \text{ atm}$, $T = 1092 \text{ K}$




0.565% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




0.565% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0$ atm, $T = 1092$ K




$0.565\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0 \text{ atm}$, $T = 1092 \text{ K}$




$0.565\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0 \text{ atm}$, $T = 1092 \text{ K}$




$0.565\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.61$, $p = 1.0 \text{ atm}$, $T = 1092 \text{ K}$




$0.588\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0 \text{ atm}$, $T = 1090 \text{ K}$




0.588% C₂H₅OH in N₂, $\Phi = 0.81$, $p = 1.0$ atm, T = 1090 K




0.588% C₂H₅OH in N₂, $\Phi = 0.81$, $p = 1.0$ atm, T = 1090 K




0.588% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0$ atm, $T = 1090$ K




0.588% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0$ atm, $T = 1090$ K




0.588% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0$ atm, $T = 1090$ K




0.588% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0$ atm, $T = 1090$ K




0.588% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0$ atm, $T = 1090$ K




0.588% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0$ atm, $T = 1090$ K




0.588% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0$ atm, $T = 1090$ K




0.588% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0$ atm, $T = 1090$ K




$0.588\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 0.81$, $p = 1.0 \text{ atm}$, $T = 1090 \text{ K}$




$0.581\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0 \text{ atm}$, $T = 1110 \text{ K}$




0.581% C₂H₅OH in N₂, $\Phi = 1.24$, $p = 1.0$ atm, T = 1110 K




0.581% C₂H₅OH in N₂, $\Phi = 1.24$, $p = 1.0$ atm, T = 1110 K




0.581% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0$ atm, $T = 1110$ K




0.581% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0$ atm, $T = 1110$ K




0.581% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0$ atm, $T = 1110$ K




0.581% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0$ atm, $T = 1110$ K




$0.581\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0 \text{ atm}$, $T = 1110 \text{ K}$




$0.581\% \text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0 \text{ atm}$, $T = 1110 \text{ K}$



0.581% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0$ atm, $T = 1110$ K



0.581% $\text{C}_2\text{H}_5\text{OH}$ in N_2 , $\Phi = 1.24$, $p = 1.0$ atm, $T = 1110$ K



0.581% C₂H₅OH in N₂, $\Phi = 1.24$, $p = 1.0$ atm, T = 1110 K

