




0.3% CH<sub>4</sub>, 6.0% O<sub>2</sub> in N<sub>2</sub>,  $\Phi = 0.1$ ,  $p = 1.0$  atm,  $\tau = 0.1$  s




0.3% CH<sub>4</sub>, 6.0% O<sub>2</sub> in N<sub>2</sub>,  $\Phi = 0.1$ ,  $p = 1.0$  atm,  $\tau = 0.1$  s



0.3% CH<sub>4</sub>, 6.0% O<sub>2</sub> in N<sub>2</sub>,  $\Phi = 0.1$ ,  $p = 1.0$  atm,  $\tau = 0.1$  s



0.3% CH<sub>4</sub>, 6.0% O<sub>2</sub> in N<sub>2</sub>,  $\Phi = 0.1$ ,  $p = 1.0$  atm,  $\tau = 0.1$  s



0.3% CH<sub>4</sub>, 6.0% O<sub>2</sub> in N<sub>2</sub>,  $\Phi = 0.1$ ,  $p = 1.0$  atm,  $\tau = 0.1$  s

