




0.15% C₂H₆ in N₂, $\Phi = 0.1$, $p = 1.0$ atm, $\tau = 0.1$ s




0.15% C₂H₆ in N₂, $\Phi = 0.1$, $p = 1.0$ atm, $\tau = 0.1$ s




0.15% C₂H₆ in N₂, $\Phi = 0.1$, $p = 1.0$ atm, $\tau = 0.1$ s




0.15% C₂H₆ in N₂, $\Phi = 0.1$, $p = 1.0$ atm, $\tau = 0.1$ s




0.15% C₂H₆ in N₂, $\Phi = 0.1$, $p = 1.0$ atm, $\tau = 0.1$ s




0.15% C₂H₆ in N₂, $\Phi = 1.5$, $p = 1.0$ atm, $\tau = 0.1$ s




0.15% C₂H₆ in N₂, $\Phi = 1.5$, $p = 1.0$ atm, $\tau = 0.1$ s




0.15% C₂H₆ in N₂, $\Phi = 1.5$, $p = 1.0$ atm, $\tau = 0.1$ s




0.15% C₂H₆ in N₂, $\Phi = 1.5$, $p = 1.0$ atm, $\tau = 0.1$ s



0.15% C₂H₆ in N₂, $\Phi = 1.5$, $p = 1.0$ atm, $\tau = 0.1$ s



0.15% C₂H₆ in N₂, $\Phi = 1.5$, $p = 1.0$ atm, $\tau = 0.1$ s



0.15% C₂H₆ in N₂, $\Phi = 1.5$, $p = 1.0$ atm, $\tau = 0.1$ s

